State of Oregon Drinking Water Program Monthly Disinfection Report for Ground Water Systems

System Name: Bella Casa Mobile Hor		Bella Casa Mobile Hon	ne Park	Park PWS ID# 41 - 01005	
Month/Year:		December 2021	Entry Point: Kitchen Sink in Rec Rm	Required Minimum Residual: 0.60 mg/L	
Date	Time	Source(s) in Use	Lowest free chlorine residual at entry point to distribution system (mg/L)	N	otes
1	2:00:00 PM	WELL (L15434)	0.78		
2	10:00:00 AM	WELL (L15434)	0.82		
3	10:00:00 AM	WELL (L15434)	0.80		
4	10:00:00 AM	WELL (L15434)	0.72		
5	6:00:00 AM	WELL (L15434)	0.70		
6	2:00:00 PM	WELL (L15434)	0.88		
7	10:00:00 AM	WELL (L15434)	0.80		
8	6:00:00 AM	WELL (L15434)	0.80		
9	6:00:00 PM	WELL (L15434)	0.72		
10	6:00:00 PM	WELL (L15434)	0.70		
11	6:00:00 PM	WELL (L15434)	0.75		
12	6:00:00 PM	WELL (L15434)	0.78		
13	10:00:00 AM	WELL (L15434)	0.81		
14	10:00:00 AM	WELL (L15434)	0.77		
15	6:00:00 AM	WELL (L15434)	0.82		
16	2:00:00 PM	WELL (L15434)	0.81		
17	2:00:00 PM	WELL (L15434)	0.84		
18	6:00:00 AM	WELL (L15434)	0.78		
19	6:00:00 AM	WELL (L15434)	0.78		
20	6:00:00 PM	WELL (L15434)	0.99		
21	10:00:00 AM	WELL (L15434)	0.97		
22	10:00:00 AM	WELL (L15434)	0.90		
23	2:00:00 PM	WELL (L15434)	0.92		
24	6:00:00 AM	WELL (L15434)	0.88		
25	6:00:00 AM	WELL (L15434)	0.85		
26	6:00:00 AM	WELL (L15434)	0.87		
27	10:00:00 AM	WELL (L15434)	0.85		
28	2:00:00 PM	WELL (L15434)	0.84		
29	2:00:00 PM	WELL (L15434)	0.81		
30	6:00:00 PM	WELL (L15434)	0.80		
31	10:00:00 AM	WELL (L15434)	0.80		
Was the chlorine residual ever less than the required minimum residual of .60 mg/L YesX_ No If yes, what was the longest time period until the required level was restored? hours					
GWS Serving 3,300 or Fewer			GWS Serving Mo	re Than 3,300	
3 2,222				•	
If yes, did you monitor every four hours until the residual returned to .60 mg/L?			Did continuous monitoring equipment fail at any time this reporting month?YesNo		Date continuous monitoring equipment failed:
Attach those results and submit them with this form.			g a quaption and a contract to contract to		Date it was returned to service:
Printe	d Name:	Dan Reitz	Title: Vice President		· ·
111110	a rituillo.	Dan Roll		Operator Cartification	#: D:6528, T:6528
Cianatura			Oregon Water Services, Inc.	Operator Certification	
Signature			Phone#: (541) 342-1718		OR
Date:	1/7/2022			Small Ground Water System	